



Below is an estimate for the repair work and reinstallation to get your well back into operations. Please let me know if you have any questions or need anything additional.

(2) new 10"	\$ 3,080.00
(12) refaced	\$ 2,000.00
(1) 10" ss coupling	\$ 250.00
(30) 10" ss spiders	\$ 3,300.00
w/ pop in 1-7/8" x 2.5"	\$ 750.00
(35') 1-11/16" SS	\$ 1,760.00
SS headshaft	\$ 415.00
Pump	\$ 11,350.00
Tailpipe & Strainer	\$ 665.00
Airlines	\$ 150.00
Transducer	\$ 1,250.00
	\$ 24,970.00

Best Regards,

Gary P. Randle II | Southeast WI. Branch Manager | CTW Corporation

Cell 414.308.0024 | Office 262.253.6613 | Fax 262.253.6887

Corporate Office | 21500 W. Good Hope Rd, Lannon, WI 53046

Email: gary.randle@ctwcorporation.com | Web: www.ctwcorporation.com